Workload Assumptions



Workload Assumptions Reset

- Technical Inspections (TI) = 2 x TI Steady State
- Corrective Maintenance = 2 x (LO + A-Service) or Sum all other
- Agricultural Cleaning = 1 bay 2 hours per day
- Receipt Transactions = 40% by line item/quantity (2-year worklo
- Issue Transactions = 40% by line item/quantity (2-year workload
- Inventory transition requirements = 100%
- 2000 class 9 requisitions per month
- Receive 250 and ship 250 ISO containers per month